

FACILITY COMPLIANCE AUDIT REPORT

Division of Waste Management Solid Waste Section

UNIT TYPE: (check all that apply to this audit with same Permit number)														
Lined MSWLF	X	LCID		YW		Transfer		Compost		SLAS		COUNTY: Haywood		
Closed		HHW		White		Incin		T&P		FIRM		PERMIT NO.: 44-07		
MSWLF				goods										
CDLF		Tire T&P /		Tire		Industrial		DEMO		SDTF		FILE TYPE: COMPLIANCE		
		Collection		Monofill		Landfill						1122 111 2: 00MI 2// (102		

Date of Audit: _11/14/08 _____ Date of Last Audit: 09/29/08 _____

FACILITY NAME AND ADDRESS:

Haywood County Municipal Solid Waste Landfill State Road 1338, White Oak Community Waynesville, N. C. 28786

GPS COORDINATES: N: 35.66343 W: -82.99866_

FACILITY CONTACT NAME AND PHONE NUMBER:

Stephen King, Haywood County Solid Waste Director Telephone 828-627-8042

FACILITY CONTACT ADDRESS (IF DIFFERENT):

Stephen King, Director Haywood County Solid Waste Department 278 Recycle Drive Clyde, N. C. 28721

AUDIT PARTICIPANTS:

Andrea Keller, NCDENR, Division of Waste Management (DWM), Solid Waste Section (SWS) Stephen King, Haywood County Solid Waste Director David Mingus, Jet Clean America

STATUS OF PERMIT:

Active-Permit to Operate issued November 8, 2006

PURPOSE OF AUDIT:

Partial audit of Municipal solid waste landfill

STATUS OF PAST NOTED VIOLATIONS:

N/A

AREAS OF CONCERN AND COMMENTS:

1. The NCDENR/DWM/SWS was notified on 9/26/08 of leachate seep and repair activities at the MSWLF. The site visit and audit on 9/29/08 documented the trenching and repair activities associated with the leachate seepage.

FACILITY COMPLIANCE AUDIT REPORT

Division of Waste Management Solid Waste Section

Page 2 of 2

1 11.

- 2. Additional corrective actions associated with the leachate seep stated that landfill personnel will continue to monitor the area and that the annual cleaning of the leachate system piping/sump area will be scheduled for the month of October. The actual date of leachate line jetting/cleaning was November 14, 2008.
- 3. During the onsite audit the subcontractor (Jet Clean America) was jetting lines on the NE side of the MSWLF while landfill personnel dug up additional cleanout locations. The contractor stated that some blockage was occurring at the location where the jetting lines had become stuck and recommended that camera work be included during next jetting/cleaning event.
- 4. During the previous audit (9/26/08) it was noted that the southern side of the MSW active working face, while seeded and with adequate ground cover, was exhibiting erosion conditions which required repair/attention. Most of the erosion gullies had been repaired/filled at the time of this audit. However, close attention should be paid to this region in the future.

Please contact me if you have any questions or concerns regarding this audit report.

_ XIIII		Phone	e: <u>828</u>	.				
Andrea Keller								
Environmental Senior Specialist								
Regional Representative								
Delivered on : 12/16/08 by		hand delivery		US Mail		Certified No. [_]		

cc: Mark Poindexter, Field Operations Branch Supervisor Deb Aja, Western District Supervisor Donald Herndon, Compliance Officer